



VIBRATION CONDITION CHECK

Unit Designation: 100 H.P. Compressor

Date: February 7, 2004



Driver

Make: Brook Crompton S/N: 3115 220 04M RPM Plate: 1770 RPM Actual: 1760 Model: K404TD H.P.: 100 Service Factor: 1.15 Running Hours: 63,648

Driven

Make: GHH S/N: 141516 RPM Plate: Not Available RPM Actual: 1760/ 3203 Model: CF1286 Load: 100 p.s.i. Gear Ratio: 1.82:1 △P: 1 p.s.i.

 \square

Admin. 222 (Rev.: 05/01)

3075 14th Avenue, Suite 216, Markham, ON L3R 0G9 Toronto Line: **(416) 606-9999** Tel.: (905) 944-9900 Fax: (905) 944-9903 www.vibtech.ca



VIBRATION CONDITION CHECK

100 H.P. Compressor			1 2	2 3	4 5	
Unit Description		No	Low		High	Don't
*		Action		PRIOR	ITY	Run
Vibration Data						
	(in/se	c. pk.)				
						ang dan jarah sa managana ang mangana
A-A A-H A-V B-				-V D-		D-V
.24 .16 .16	070 .086	1.18 .	15 .1		7 .15	.10
E-A E-H E-V F-	-A F-H F-V	G-A (G-H G	-V H-	A H-H	H-V
.13 .27 .19 .19	5 .27 .20		91 1.	3	29	2.1

Comments

The overall vibration levels measured on the compressor and motor are within acceptable limits, however, the cooling fan motor is vibrating excessively. The cooling fan is severely unbalanced, which is the primary source of the vibration.

The compressor bearings appear to be in good mechanical condition, however, the drive end motor bearing is showing moderate to advanced wear. The cooling fan motor bearings are in good condition as well.

The compressor base is not isolated from the floor.

Recommendations

- 1.) Shop balance the cooling fan and motor, as a unit.
- 2.) Periodically monitor the condition of the motor bearings. Replace the drive end motor bearing when convenient.
- 3.) Install vibration isolation pads under the compressor base frame.

tech Analysis L Keeping Canadian Companies Competitive