



DESCRIPTION	DATE
Contactor	Sept. 25, 2003

Identification: SF-20

INFRARED IMAGE



PHOTO



IR information	Value
Date of creation	9/25/03
Object parameter	Value
Ambient temperature	22.0°C

Current Measured at Time of Inspection
5 A, 5 A, 5 A

DESCRIPTION:
<p>An InfraRed image of a contactor located inside SF-20 control panel, located in the B1 mechanical room. <u>No heat related problems were noted.</u></p> <p>Our visual inspection noted a broken coil retaining clip (at green arrow in photo).</p> <p>See IR information chart above for maximum temperature located inside the area box (AR01).</p>

Priority:

RECOMMENDATION:			1	3	4	5		
	No Action	Low					High	Don't Run

<p>Replace the broken coil retaining clip.</p> <p>Re-inspect the unit after the repairs are completed.</p>
--