

Priority Trending Report

Book	Section	Unit Designation	April 02	June 02	Oct. 02	May 03	Nov. 03	Jan. 04
A	10	CV-029				3, 2	0, 0	
A	20	CV-030	4	0				
A	30	CV-031			2	0		
A	40	CV-027						
A	50	Recipricator Panel				N/C	N/C	
A	60	CV-028						
A	70	CV-087					5	0
A	80	CV-032, Service B-5						
A	90	CV-033						
A	100	CV-032	4	3, 3	4	0		
A	110	CV-118 Left Panel, Service B-7C						
A	120	CV-118 Right Panel	4	0, 3	4	0, 3	0	
A	130	CV-117 Left Panel			2	0, 2, 2	0, 0	
A	140	CV-117 Right Panel	4	2	3, 3	0, 0, 3	0	
A	150	CV-038-6					N/C	
A	160	CV-038-5						
A	170	CV-037-4						
A	180	CV-037-3	3	0		0		
A	190	CV-036-2						
A	200	Mega Panel				2	3, 0	0
A	210	Mega Panel B				2	0	
A	220	CV-039	3, 2	3	3	0		
A	230	CV-046						
A	240	Service B-7						
A	250	CV-046 Supply						
A	260	CV-039 Supply						
A	270	Services B-7B	2	2		2	3	3
A	280	CV-062 Supply				2	0	
A	282	CV-040						
A	284	CV-051						
A	286	CV-053				N/C		
A	288	CV-054						
A	290	Battery Charger XF						
A	300	CV-036 Supply					3	0
A	310	Service B-7A						
A	320	Bus Duct B-7C						
A	330	CV-042						

Note: Machines with no priority noted have been checked and have a priority of "0".
Machines not checked have "N/C" recorded and the priority box lightly shaded.
Solidly shaded areas indicate machines not on follow-up list to be checked.